

Mode	Model	Equipment St	Description	Task Type	Workorder Number	Status	Completed On
	672G	GR29	minor work orders for minelink june 2023	GR - General Repair	CVW66738-2301	C	13/07/2023 13:13
	672G	GR29	re shim A frame ball	GR - General Repair	CVW67653-2301	C	13/07/2023 13:13
	672G	GR29	STEERING CYLINDER RH	GR - General Repair	CVW57781-2301	C	13/07/2023 13:13
	672G	GR29	adjust circle	GR - General Repair	CVW67656-2301	C	13/07/2023 13:03
	672G	GR29	replace broken steps on access ladder	GR - General Repair	CVW67655-2301	C	4/07/2023 15:24
	672G	GR29	replace blade slides	GR - General Repair	CVW67654-2301	C	4/07/2023 12:29
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW54200-2105	C	4/03/2023 11:12
	672G	GR29	flat battery	GR - General Repair	CVW35266-2208	C	20/02/2023 14:35
	672G	GR29	FIRE EXTINGUISHER	GR - General Repair	CVW61072-2205	C	1/02/2023 13:58
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW58561-2207	C	30/01/2023 11:42
	672G	GR29	blade slides need adjusting	GR - General Repair	CVW59551-2205	C	22/11/2022 10:45
	672G	GR29	(ACC ) Blade sensor for trimble dislodged	ACC - Accident Damage	CVW59552-2205	C	17/11/2022 8:58
	672G	GR29	exhaust manifold leaking between bellows	GR - General Repair	CVW66715-2301	C	9/11/2022 15:18
	672G	GR29	error code code...vgt actuator out of range.	GR - General Repair	CVW57381-2111	C	8/11/2022 15:18
	672G	GR29	engine shut down wont restart	GR - General Repair	CVW60869-2205	C	7/11/2022 15:18
	672G	GR29	500 HOUR SERVICE	PM - Servicing	CVW59404-2203	C	2/11/2022 11:12
	672G	GR29	(ACC) two way arial connection broken off	ACC - Accident Damage	CVW60435-2204	C	26/10/2022 10:57
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW48361-2203	C	6/10/2022 13:35
	672G	GR29	wiper blades need replacing	GR - General Repair	CVW58643-2202	C	8/08/2022 15:31
	672G	GR29	cutting edge needs replacing.	G.E.T - Ground Engaging Tools	CVW58466-2201	C	8/08/2022 15:00
	672G	GR29	ignition fault	GR - General Repair	CVW55470-2108	C	25/07/2022 9:00
	672G	GR29	2000 HOUR SERVICE	PM - Servicing	CVW57617-2201	C	18/07/2022 13:34
	672G	GR29	grease pod cracked and leaking grease	ACC - Accident Damage	CVW57608-2202	C	12/07/2022 14:36
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW56219-2111	C	21/06/2022 8:38
	672G	GR29	FIRE EXTINGUISHER	GR - General Repair	CVW56690-2110	C	12/06/2022 12:22
	672G	GR29	P1 Tyre oring replaced	GR - General Repair	CVW46351-2111	C	25/05/2022 12:28
	672G	GR29	circle needs adjusting	GR - General Repair	CVW52838-2102	C	31/03/2022 15:14
	672G	GR29	blade slides need adjusting.	GR - General Repair	CVW55324-2108	C	30/03/2022 15:13
	672G	GR29	horn not working	GR - General Repair	CVW55755-2108	C	15/02/2022 12:33
	672G	GR29	500 HOUR SERVICE	PM - Servicing	CVW55314-2108	C	14/02/2022 11:39
	672G	GR29	1000 HOUR SERVICE	PM - Servicing	CVW62136-2301	C	20/01/2022 9:58
	672G	GR29	air cond works intermittently.	GR - General Repair	CVW55447-2107	C	19/01/2022 9:58
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW43802-2105	C	8/12/2021 11:50
	672G	GR29	FIRE EXTINGUISHER	GR - General Repair	CVW52334-2101	C	1/11/2021 13:55
	672G	GR29	1000 HOUR SERVICE	PM - Servicing	CVW52387-2103	C	22/09/2021 18:00
	672G	GR29	oil leak RHS of rear drive	GR - General Repair	CVW53243-2103	C	7/09/2021 15:40
	672G	GR29	blade slides shims missing	WEAR - Wear Part	CVW52797-2102	C	11/08/2021 13:00
	672G	GR29	Not starting	GR - General Repair	CVW52734-2102	C	4/08/2021 9:22
	672G	GR29	fan belt shredding (one rib missing)	GR - General Repair	CVW45296-2002	C	13/07/2021 7:39
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW45808-2004	C	1/06/2021 10:03
	672G	GR29	FIRE EXTINGUISHER	GR - General Repair	CVW41683-1906	C	6/02/2021 13:46
	672G	GR29	(ACC) Light broken spotlight	ACC - Accident Damage	CVW48087-2006	C	9/12/2020 11:00
	672G	GR29	500 HOUR SERVICE	PM - Servicing	CVW47143-2006	C	7/12/2020 15:37
	672G	GR29	Control lever switch faulty	GR - General Repair	CVW44645-2005	C	14/11/2020 8:29
	672G	GR29	Cutting edges worn	G.E.T - Ground Engaging Tools	CVW45190-2002	C	30/07/2020 13:27
	672G	GR29	2000 HOUR SERVICE	PM - Servicing	CVW44736-2002	C	27/07/2020 15:51
	672G	GR29	(ACC) music arial broken/UHF also	GR - General Repair	CVW44409-1912	C	23/06/2020 8:47
	672G	GR29	Blade side shift ram weeping	GR - General Repair	CVW46270-2301	C	17/06/2020 11:50
	672G	GR29	Auto grease system not working	GR - General Repair	CVW43393-1910	C	16/06/2020 11:50
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW41799-1912	C	13/06/2020 10:53
	672G	GR29	radio fuse has been removed	GR - General Repair	CVW44154-1912	C	2/06/2020 10:00
	672G	GR29	position 2 tyre staked (accident damaged)	ACC - Accident Damage	CVW43748-1911	C	6/05/2020 13:35
	672G	GR29	500 HOUR SERVICE	PM - Servicing	CVW40219-1909	C	1/04/2020 15:26
	672G	GR29	Electric fuel transfer pump failed	CC - Component Change Out	CVW41787-1907	C	6/01/2020 10:40
	672G	GR29	circle drive gearbox bad oil sample	GR - General Repair	CVW40248-1903	C	25/10/2019 7:38
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW39542-1901	C	19/08/2019 12:31
	672G	GR29	Fit 4 x new drive tyres as current un matched	GR - General Repair	CVW39882-1903	C	5/08/2019 11:00
	672G	GR29	TYRE	GR - General Repair	CVW30594-1709	C	5/08/2019 11:00
	672G	GR29	TYRE	GR - General Repair	CVW30595-1709	C	5/08/2019 11:00
	672G	GR29	TYRE	GR - General Repair	CVW30597-1709	C	5/08/2019 11:00
	672G	GR29	Requires G.E.T & scarifier tips	GR - General Repair	CVW39640-1902	C	5/08/2019 10:24
	672G	GR29	position 3 tyre punched on inside sidewall (STAKED)	ACC - Accident Damage	CVW39820-1901	C	30/07/2019 13:30
	672G	GR29	Grease system faulty	LU - Lubrication	CVW39561-1901	C	19/07/2019 14:00
	672G	GR29	FIRE EXTINGUISHER	GR - General Repair	CVW39743-1901	C	8/07/2019 11:07
	672G	GR29	1000 Service Hour Maintenance	PM - Servicing	CVW30589-1812	C	29/06/2019 13:51
	672G	GR29	Replace Acc Belt , Tensioner, and Idlers	GR - General Repair	CVW39199-1901	C	5/06/2019 13:00
	672G	GR29	Trimble requires calibration and valve speed check	GR - General Repair	CVW38041-1806	C	13/04/2019 9:20
	672G	GR29	Adjust Circle	GR - General Repair	CVW38876-1809	C	11/04/2019 13:50
	672G	GR29	FIRE EXTINGUISHER	GR - General Repair	CVW36880-1803	C	19/03/2019 9:08
	672G	GR29	250 HOUR SERVICE	PM - Servicing	CVW38525-1808	C	9/03/2019 13:00
	672G	GR29	Change cutting edges (& Parts for WT17 Air Line)	GR - General Repair	CVW38288-1808	C	7/02/2019 13:00
	672G	GR29	500 HOUR SERVICE	PM - Servicing	CVW37989-1806	C	12/01/2019 12:00
	672G	GR29	FIRE EXTINGUISHER	GR - General Repair	CVW36846-1803	C	12/09/2018 9:30
	672G	GR29	250 Service Hour Maintenance	PM - Servicing	CVW30587-1802	C	3/09/2018 12:00
	672G	GR29	(ACC) LH E stop replacement	ACC - Accident Damage	CVW36425-1802	C	29/08/2018 13:00
	672G	GR29	requested Slope meter to be fitted	GR - General Repair	CVW36073-1802	C	23/08/2018 8:00
	672G	GR29	2000 Service Hour Maintenance	PM - Servicing	CVW30590-1801	C	6/07/2018 7:33
	672G	GR29	Low Fuel Pressure	GR - General Repair	CVW34909-1711	C	6/06/2018 11:06
	672G	GR29	position 1 tyre flat	GR - General Repair	CVW30592-1710	C	15/05/2018 8:37
	672G	GR29	Pos 2 tyre change out	GR - General Repair	CVW30593-1710	C	15/05/2018 8:36
	672G	GR29	G.E.T Edges & Sacrificer Tips	GR - General Repair	CVW34471-1711	C	7/05/2018 11:08
	672G	GR29	Blade Slides	GR - General Repair	CVW31942-1709	C	20/04/2018 20:46
	672G	GR29	500 Service Hour Maintenance	PM - Servicing	CVW30588-1709	C	7/04/2018 16:00
	672G	GR29	position 4 tyre o ring leaking	GR - General Repair	CVW17404-1707	C	29/01/2018 17:50
	672G	GR29	oil leak on both tandem drive case pivots , oil leak on both sides drive case to machine	GR - General Repair	CVW58977-2301	C	