

Machine Disposal Report

Fleet: EX02

Model: 345DL

Serial Number: PBT00315

	Hour Meter Reading	Date:	Component Code	Description:	Repair Type:
CHASSIS	5343	2/04/2015	IMPLEMENTS / WORK TOOLS / CIRCLES	EX 02 HITCH weld and remachine quick hitch bores (2 runs required) weld and remachine quick banana link bores	Minor Repair
	5343	24/03/2015	IMPLEMENTS / WORK TOOLS / CIRCLES	2* 087-5548 bearings	Minor Repair
	5343	24/03/2015	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv. # PI9545488 2* 2285619 bearings	Minor Repair
	5343	24/03/2015	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv. # PI9550854 Freight	Minor Repair
	5292	18/03/2015	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv. # PI9530631 1* 235-7628 PIN AS	Minor Repair

CHASSIS	5292	18/03/2015	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv. # PI9550847 1* 5B-0651 FITTING 2* 367-8470 SEAL-LINKAGE 1* 235-7636 PIN AS 1* 235-7642 PIN AS 2* 7Y-2397 BEARING 6* 9X-4597 SEAL LIPTYPE 2* 367-8468 SEAL-LINKAGE 6* 447-1707 BOLT HEX HEA 6* 7X-0513 WASHER 2* 4I-6897 BRG SLEEVE 2* 228-5619 BEARING-SLVE 2* 166-1494 SEAL 2* 9X-4598 SEAL Freight	Minor Repair
	4572	5/11/2014	BUCKET / BLADE	Repaired cracks in batter bucket Repaired broken handrails and handrail mounting bolts Retapped mounts and rebolted Repaired broken handrail supports	Minor Repair
	6886	19/09/2013	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv PI8202420 10 1K-1709WASHER 10 Melbourne (10 day) 17.24 172.40 2 3J-6216WASHER 6* 1900627 shim 8* 1944175 bearing 2* 2534645 shaft 4* 0951235 nut 4* 2h3772 cotter 4* 7x7740 washer	Minor Repair
	6886	19/09/2013	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv PI8199735 10 8D-3267WASHER 10 In stock 18.72 187.20 + Cat A/F Charge	Minor Repair

CHASSIS	6802	5/09/2013	BOWL / TRAY	EX02 - GP Bucket Repairs 1 Collected bucket from site 1 Removed worn wear plates and lip protection 1 Welded arrow head and grouser bar to protect lip 1 Welded X10 heel blocks to prevent wear 1 Repaired cracks around adaptors 1 Welded I.D. plate onto bucket 11 Labour 2600.00 1 260.00 2860.00 Welding wire 90.00 1 9.00 99.00 Gas 155.00 1 15.50 170.50 Grouser Bar 129.00 1 12.90 141.90 Heel blocks 1260.00 1 126.00 1386.00 I.D. plates 18.00 1 1.80 19.80	Minor Repair
	6710	21/08/2013	OPERATORS STATION	Tax Inv PI8129377 5* 170-9724 CLIP + Cat A/F Charge	Minor Repair
	6710	21/08/2013	OPERATORS STATION	Tax Inv PI8132362 1* 234-6549 COVER	Minor Repair
	6536	18/07/2013	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv PI8046026 Cat A/F Charge	Minor Repair
	6536	18/07/2013	IMPLEMENTS / WORK TOOLS / CIRCLES	Tax Inv PI8050427 2* 236-2843 HOSE AS 1* 236-2848 HOSE AS 1* 245-5079 HOSE AS 1* 289-5657 HOSE AS	Minor Repair
	6536	16/07/2013	IMPLEMENTS / WORK TOOLS / CIRCLES	2* 4I-9521 BAND 2* 4I-9522 BAND 2* 4I-9523 BAND 2* 4I-9524 BAND 1* 236-2844 HOSE AS	Minor Repair
	6513	6/07/2013	IMPLEMENTS / WORK TOOLS / CIRCLES	DAMAGED METAL PIPE ON HYDRAULIC RAM REMOVED METAL PIPE INSTALLED 1X NEW RUBER HOSE	Minor Repair

CHASSIS	6476	1/07/2013	CENTER HITCH / OSCILLATION POINT	OIL LINE TO QUICK HITCH BLOWN REMOVED HOSE DROVE TO MEET HOSE DOCTOR HAD HOSE MADE UP AND DROVE BACK, FITTED HOSE RE ROUTED HOSE TO PRVENT FAILURE AGAIN.	Minor Repair
	6220	15/05/2013	BUCKET / BLADE	REMOVE, REMAKE AND REFIIT HOSE. EXCUVATOR BUCKET PIVOT - BUTLER EX02	Minor Repair
	6162	24/04/2013	IMPLEMENTS / WORK TOOLS / CIRCLES	1* 345D ripper attachment	Capital Expense
	5960	13/03/2013	BUCKET / BLADE	removed bucket off digger for transportation	Minor Repair
	5923	5/03/2013	BUCKET / BLADE	EX02 - Batter Bucket Inspected stick and created templates for centre gussets Removed centre gussets and ground up bucket Tacked 25mm Bis 400 gussets into position Pre-heated and fully welded internal gussets Tacked heal blocks into position, pre-heated and fully welded Repaired large cracks in bucket shell, top pressing and around ears Built up welds in side cutters 1	Minor Repair
	5620	19/12/2012	CENTER HITCH / OSCILLATION POINT	Attend on site, Honey Wood and replace quick hitch hoses on excavator as requested.	Minor Repair
	5588	8/12/2012	BUCKET / BLADE	EX02 - Batter Bucket Heel blocks - waiting on bucket availability	Minor Repair
	5411	6/11/2012	BUCKET / BLADE	EX02 - Baldvis Examined batter bucket, measured and ordered steel and heel blocks Fuel	Minor Repair
	4861	23/07/2012	OPERATORS STATION	Tax Inv PI7174342 2x 6V-7238 valve + cat a/f charge	Minor Repair
	4861	23/07/2012	OPERATORS STATION	Tax Inv PI7177963 2x 8Y-6967 lover as	Minor Repair

CHASSIS	3141	22/02/2012	OPERATORS STATION	1* WINDSCREEN REPAIR - MELIA TO DELIVER	Minor Repair
	3141	22/02/2012	PANEL AND PAINT	1x 183-1035 lamp	Minor Repair
	3141	21/12/2011	BUCKET / BLADE	Tax Inv PI6670560 01c559950 1X 1D-4637 BOLTS 10X 2J-3507 NUTS 10X 3K-5234 WASHERS	Minor Repair
	3141	21/12/2011	BUCKET / BLADE	Tax Inv PI6670561 01c559950A 1X 1D-4637 BOLTS 1X 256-8691 SIDE CUTTERS R/H	Minor Repair
	3141	21/12/2011	BUCKET / BLADE	Tax Inv PI6670562 01c559950B 1x 256-8690 side cutter	Minor Repair
	3141	21/12/2011	BUCKET / BLADE	Tax Adjustment Credit Note PC0465309 01c559950 1X 1D-4637 BOLTS	Minor Repair
	3141	21/12/2011	BUCKET / BLADE	Tax Adjustment Credit Note PC0466115 1X 256-8691 SIDE CUTTERS R/H	Minor Repair
	2827	10/11/2011	BUCKET / BLADE	PHOTOS OF EX02 BEFORE GOING TO COOLGARDIE SITE	Minor Repair
	2327	6/09/2011	BUCKET / BLADE	to repair batter bucket as required due to used in the incorrect application	Operator Damage
	2064	5/08/2011	BUCKET / BLADE	TO REPAIR CRACKS IN BATTER BUCKET FISH PLATE GUSSETS	Minor Repair
	1764	13/06/2011	OPERATORS STATION	1x 161 3668 wiper assem	Minor Repair

CHASSIS	1050	16/02/2011	OPERATORS STATION	<p>TO SUPPLY AND INSTALL 1X COMPLETE SET OF WINDOW SECURITY COVERS ON A CATERPILLAR D345DL EXCAVATOR SERIAL NUMBER PBT00315</p> <p>SITE CONTACT DETAILS STEVE SMITH 0448 798 319</p> <p>SITE LOCATION CAMBOURNE PARKWAY BUTLER</p>	Minor Repair
ELECTRICAL	5220	4/03/2015	ELECTRICAL REPAIR	<p>EX 02</p> <p>25/02/2015 & 26/02/2015 Whistling Grove Compound ; Diagnose air/con sytem complete with gauges. Order parts via workshop and pick up from Westrac. Remove condenser and fan assy complete. Fit condenser fan to new condenser assy and rfit. Remove old, and fit new rec/dryer assy. Remove necessary internal cab covers and seat assy. Remove necessary cab belly covers. Disconnect heater and a/c hoses to suit. Disconnect necessary wiring. Remove old, and fit new HVAC assy complete. Reconnect hoses, wiring etc. Replace oil and o'rings to suit system. Evacuate system and leak test with gauges. Regass system and performance test. Reassemble complete. \$1,320.00 GST</p> <p>S/F</p> <p>asst x oil, o'rings, cleaner, misc \$20.35 GST</p> <p>1.3 x R134A Refrigerant \$55.06 GST</p> <p>2 x Shared travel \$83.60 GST</p>	Minor Repair
	5193	25/02/2015	AIR CONDITIONING	<p>1* 316-8917 COND GP</p> <p>1* 176-1902 RECEIVER AS</p> <p>1* 273-5307 FAN AS</p> <p>1* 245-7866 CONDENSER AS</p>	Minor Repair
	5152	19/02/2015	ELECTRICAL REPAIR	<p>Whistling Grove Compound ; R/r necessary covers etc. Diagnose and performance test air/con system complete with gauges etc. System efficient and operating within manufactures specifications. Reassemble complete.</p> <p>1 x Shared travel</p>	Minor Repair
	4733	27/11/2014	ELECTRICAL REPAIR	<p>2* ACX2123 24V BEACON</p> <p>2* LIGHT BULB TO SUIT</p>	Minor Repair

ELECTRICAL	4523	27/10/2014	ELECTRICAL REPAIR	30/09/2014 ; Lat 32 R/r necessary covers. Diagnose air/con system complete with gauges. Condenser fan failure. Order required parts via work shop. Reassemble so can be operated. 1 x Shared Travel 01/10/2014 ; Lat 32 Pick up parts via Westrac. Remove necessary condenser guards, cover's and brackets etc. Fit new condenser fan mtr assy. Reassemble and performance test air/con system. Diagnose UHF circuits. Replace UHF and AM/FM aerials. Reassemble complete. S/F 1 x UHF S/S aerial & AM/FM whip arial 1 x Shared Travel	Minor Repair
	4370	30/09/2014	AIR CONDITIONING	1* 4252717 motor	Minor Repair
	3513	11/03/2014	STARTER MOTOR / ALTERNATORS	EX.02 Supply to Balcatta depot 1x 24v 11th Delco Remy Starter Motor	Minor Repair
	3420	18/02/2014	STARTER MOTOR / ALTERNATORS	NOT STARTING STARTER MOTOR U/S REPLACE STARTER MOTOR	Minor Repair
	3377	11/02/2014	BATTERIES	2* 3T-5760 BATTERY	Minor Repair

ELECTRICAL	3343	31/01/2014	BATTERIES	<p>EX.02 Theft damage: Vale Compound via Westrac source batteries. Clean out battery tray. Fit new batteries. Replace eyelets to battery cables. Make up new joiner cable. Fit four new battery terminals. Secure batteries. GST Replace deutsch plug to quick hitch wiring. Reassemble & test complete. \$412.50 GST S/F 4x HD battery terminals 4x HD eyelets \$48.40 GST asst OOPS battery cable, H/shrink, deutsch plug, misc \$25.85 GST 1x shared travel</p>	Minor Repair
	3107	5/12/2013	ELECTRICAL REPAIR	<p>1 309-5795 SWITCH AS PBT00315 0.2 1 In stock 78.01 78.01 1 309-5769 SWITCH AS-PR</p>	Minor Repair
	6943	6/10/2013	ELECTRICAL REPAIR	<p>EX.02 Johnson Rd. Wellard: Remove from behind seat necessary brackets, covers, radio & window lock etc. Diagnose reducer wiring & repair. Prep for new stereo & replace necessary deutsch plugs. Fit new cat rear assy & retainers & clips. GST Refit UHF bracket & new pwr/ lead to suit. Fit new AM/FM stereo to suit. Reassemble & test complete. \$530.00 GST S/F asst x 2pin & 4pin D/plugs & pins,tape, ties, wire \$19.50 GST 1x AM/FM multi voltage stereo \$135.00 GST 1x shared travel \$42.25 GST</p>	Minor Repair

ELECTRICAL	6802	2/09/2013	TWO WAY REPAIRS	EX.02 08.08.2013: Golf Course Estate R/r rear internal pannels (damaged). Locate & rectify UHF wiring to suit. Reassemble. Order required parts \$319.00 GST S/F asst x deutsch plug/ pins/ misc \$3.85 GST 1x shared travel \$12.65 GST	Vandalism
	6354	7/06/2013	ELECTRICAL REPAIR	EX.02 Lot 8: Trace and test greasor wiring to unit. Test press/ switch, press/ relief wiring. Rectify pump pulse/ timer connections Reassemble and test complete \$236.50 GST 1x shared travel \$6.60 GST	Minor Repair
	5923	6/03/2013	ELECTRICAL REPAIR	diagnose revolving light replace H1 globe	Minor Repair
	4861	6/08/2012	AIR CONDITIONING	diagnose a/c system r/r fan belt and fit new r/r compressor assy and fit new and replace o rings fit and clamp all new a/c hoses from compressor, reciever drier condensor etc. Fit new a/c, heater evac CAT unit complete. Reconnect system test complete.	Minor Repair
	4473	13/07/2012	AIR CONDITIONING	Tax Inv PI7152023 1* 293-1183 FILTER AS	Major Repair
	4473	13/07/2012	AIR CONDITIONING	Tax Inv PI7152022 1* 305-0325COMPRESSOR 1* 221-3775 BELT 1* 293-1137 FILTER AS	Major Repair
	4473	13/07/2012	AIR CONDITIONING	Tax Inv PI7152024 1* 316-8917COND GP	Major Repair

ELECTRICAL	4473	9/07/2012	AIR CONDITIONING	Tax Inv PI7142375 1* 229-9123 HOSE 1* 229-9124 HOSE	Minor Repair
	4473	9/07/2012	AIR CONDITIONING	Tax Inv PI7138719 1* 176-1902 RECEIVER 1* 229-9121 HOSE 1* 229-9122 HOSE + Cat A/F Charge	Minor Repair
	4473	3/07/2012	AIR CONDITIONING	diagnose air/con complete with gauges. Trace external air/con hoses and components with UV lamp. No trace of UV dye. Add hychill hydracarbon refrigerant with UV dye and performance test so machine can be used	Minor Repair
	4473	3/07/2012	ELECTRICAL REPAIR	diagnose revolving light circuit. R/r and fit new hella revolving lamp to suit. Reaseamble and test complete.	Minor Repair
	4226	7/05/2012	AIR CONDITIONING	diagnose air/con system complete with gauges. Regass system with hychill so machine can be used. Snake pit to be cleaned out to allow for A/C hose inspection. Reassemble internal covers. Solder UHF coax cable to plug Asst X Hychill/ hyd cable/ refrigerant 1x shared travel	Minor Repair
	3141	14/02/2012	AIR CONDITIONING	1x 293-1137 a/c filter	Minor Repair
	3141	3/02/2012	AIR CONDITIONING	Tax Inv PI6759266 2x 245-7823 cab filters	Minor Repair
	3141	3/02/2012	AIR CONDITIONING	Tax Inv PI6759267 2x 293-1184 cab filters	Minor Repair
	3141	9/01/2012	BATTERIES	2x 3T5760 battery	Minor Repair
	2827	17/11/2011	ELECTRICAL REPAIR	ELECTRICAL SCHMATIC FOR EX02 385C	Minor Repair
	2421	14/10/2011	ELECTRICAL REPAIR	1X 221-3775 ALTERNATOR BELT	Minor Repair
	2421	7/10/2011	ELECTRICAL REPAIR	Remove and replace new Hella light	Minor Repair

ELECTRICAL	1897	4/07/2011	ELECTRICAL REPAIR	to repair warning horn fault	Minor Repair
	1720	11/06/2011	ELECTRICAL REPAIR	WIPERS REPAIRS AS PER ATTACHED	Minor Repair
	1639	27/05/2011	ELECTRICAL REPAIR	TO REPAIR DEFECTIVE WORK LIGHTS	Minor Repair
	964	31/01/2011	ELECTRICAL REPAIR	Invoice Number 4926 to repair u-s flashing light	Minor Repair
	493	4/11/2010	TWO WAY REPAIRS	TO REPAIR UHF WIRING AND SUPPLY PARTS STOLEN WHEN MACHINE HAS BEEN BROKEN IN TO	Vandalism
ENGINE	4572	4/11/2014	ENGINE REPAIR	1 163 9361 oil filler cap	Minor Repair
	7572	26/03/2014	ENGINE REPAIR	LOW ENGINE OIL PRESSURE MONITOR LOW OIL PRESSURE, INTERMITTENTLY DROPPING TO 30PSI @ HIGH IDLE CARRY OUT THE FOLLOWING REPAIRS AND INSPECTIONS REMOVE SUMP AND INSPECT OIL PICK UP, REMOVE MAIN BEARING CAP AND CHECK FOR WEAR AND EXCESS HEAT ALL OK REPLACE OIL PRESSURE SENSOR AND CHECK WIRING REMOVE ROCKER COVER, INSPECT ROCKER SHAFTS FOR BREAKAGES OR BROKEN BOLTS REPLACE OIL PUMP BYPASS VALVE AND INSPECT OIL FILTER AND COOLER BYPASS VALVES REPLACE OIL COOLER AND OIL FILTER BASE GROUP CHECK PRESSURE AFTER REPAIRS LOW IDLER 40PSI	Minor Repair

ENGINE	3456	27/02/2014	ENGINE REPAIR	Tax Invoice No. PI 8577034 1 227-4892 GASKET + 7LN00242 0.3 1 In stock 8.45 8.45 2 113-5304 SEAL + 7LN00242 0.4 2 In stock 16.10 32.20 1 1R-1808 FILTER AS-LU 7LN00242 3.9 1 In stock 33.08 33.08 1 213-9396 SEAL-O-RING + 7LN00242 0.1 1 In stock 4.56 4.56 2 2N-5243 SEAL O RING + 7LN00242 0.2 2 In stock 3.94 7.88 1 6V-9027 SEAL-O-RING + 7LN00242 0.1 1 In stock .74 .74 1 9S-8002 PLUG 7LN00242 0.1 1 In stock 4.12 4.12 1 6V-3251 SEAL O RING + 7LN00242 0.1 1 In stock 1.08 1.08 1 9S-8006 PLUG 7LN00242 0.1 1 In stock 6.18 6.18 1 6V-5063 SEAL O RING + 7LN00242 0.1 1 In stock 1.33 1.33 1 9S-8008 PLUG 7LN00242 0.2 1 In stock 2.60 2.60 1 6V-5064 SEAL O RING + 7LN00242 0.1 1 In stock 1.55 1.55 1 9S-9334 PLUG 7LN00242 0.3 1 In stock 8.98 8.98 1 117-3036 O RING + 7LN00242 0.1 1 In stock 4.11 4.11 1 20R-1861 CORE AS OCLR 7LN00242 28.6 1 In stock 1,180.82 1,180.82 CORE CHARGE Cat a/f Charge	Minor Repair
	3456	27/02/2014	ENGINE REPAIR	Tax Invoice No. PI8577035 1 251-6669 BASE GP 7LN00242 11.0 1 Melbourne 437.84 437.84	Minor Repair
	3456	27/02/2014	ENGINE REPAIR	Adjustment Note No. PC0577009 1* 20R-1861 CORE AS OCLR 1* 20R-1861 FULL CREDIT	Minor Repair

ENGINE	3456	25/02/2014	ENGINE REPAIR	1* 217-3673 SEAL-ISOLATI + 2.0 1 In stock 107.66 107.66 2* 3E-8016 BOLT LOCK 0.2 2 In stock .51 1.02 1* 5P-8211 SEAL + 0.1 1 In stock 11.54 11.54 2* 5P-8245 WASHER-HARD 0.2 2 In stock .53 1.06 2* 6A-5591 BOLT 0.2 2 In stock .54 1.08 2* 9M-1974 WASHER 0.2 2 In stock .24 .48 1* 7C-3954 SPRING AS 0.2 1 In stock 28.80 28.80 1* 224-3405 VALVE-PUMP B	Minor Repair
	3456	25/02/2014	ENGINE REPAIR	1* 217-3673 SEAL-ISOLATI 2* 3E-8016 BOLT LOCK 1* 5P-8211 SEAL 2* 5P-8245 WASHER-HARD 2* 6A-5591 BOLT 2* 9M-1974 WASHER 1* 7C-3954 SPRING AS 1* 224-3405 VALVE-PUMP B	Minor Repair
	3456	24/02/2014	ENGINE REPAIR	1* 194-6725 SENSOR	Minor Repair

ENGINE	3456	21/02/2014	ENGINE REPAIR	1 346-4897 SEAL-O-RING + PBT00315 0.1 1 In stock 9.83 9.83 1 3E-6788 SEAL-O RING + PBT00315 0.1 1 In stock 7.94 7.94 2 5P-8068 SEAL + PBT00315 0.2 2 In stock 12.66 25.32 1 6V-3834 SEAL O RING + PBT00315 0.1 1 In stock 14.29 14.29 3 6V-5134 SEAL O RING + PBT00315 0.3 3 In stock 10.92 32.76 5 6V-5221 BOLT PBT00315 0.5 5 In stock .70 3.50 1 8J-4351 SEAL-O-RING + PBT00315 0.1 1 In stock 10.39 10.39 8 9M-1974 WASHER PBT00315 0.8 8 In stock .24 1.92 1 10R-2296 PUMP GP OIL PBT00315 7.3 1 In stock 417.93 417.93 CORE CHARGE ++ 680.26 680.26 1 117-0067 ELBOW PBT00315 0.1 1 In stock 9.43 9.43 1 214-7566 SEAL-O-RING + PBT00315 0.1 1 In stock 3.31 3.31 1 274-6719 SENSOR GP-PR + PBT00315 0.1 1 In stock 161.78 161.78 1 3J-7354 SEAL O RING + PBT00315 0.1 1 In stock .76 .76 1 237-0227 PLUG AS-CONN PBT00315 0.1 1 In stock 2.22 2.22 1 214-7566 SEAL-O-RING	Minor Repair
	3456	21/02/2014	ENGINE REPAIR	Adjustment Note No. PC0575640 1* 10R-2296 FULL CORE RETURN	Minor Repair
	3751	18/12/2013	ENGINE REPAIR	1 x 4095523 GASKET 2 x 4095541 'O'RINGS	Minor Repair
	3751	16/12/2013	FUEL SYSTEM	1* 349-7059 CAP AS-FUEL	Minor Repair
	3726	10/12/2013	COOLING SYSTEM	TAX INV PI8394431 1 5D-8159 PIN A 1.2 11 In stock 2.04 24.48 1 Bunbury Branch 1 230-2975 SCREEN AS 3.6 1 Melbourne (10 day) 331.22 331.22 1 245-9246 SCREEN AS	Minor Repair

ENGINE	3726	10/12/2013	COOLING SYSTEM	TAX INV PI8391168 11 5D-8159 PIN A 1.2 11 In stock 2.04 24.48 1 Bunbury Branch + CAT A/F CHARGE	Minor Repair
	3726	10/12/2013	COOLING SYSTEM	TAX INV PI8400004 1 245-9183 SCREEN AS 0.9 1 Singapore (90 days) 219.78 219.78	Minor Repair
	3726	10/12/2013	COOLING SYSTEM	TAX INV PI8411648 1 230-2974 SCREEN AS 3.8 1 Morton USA (90 days) 351.16 351.16	Minor Repair
	3107	4/12/2013	COOLING SYSTEM	1 248-5513 REGULATOR-TE 1 227-5075 SEAL-PRESS 1 3S-9643 SEAL	Minor Repair
	3082	28/11/2013	COOLING SYSTEM	TAX INV PI8365254 1 383-6407 CORE AS-RADI PBT00315 - 1 Melbourne (10 day) 1,834.22 1,834.22	Major Repair
	3082	28/11/2013	COOLING SYSTEM	TAX INV PI8362569 1 230-2970 CAP AS PBT00315 0.2 1 In stock 15.36 15.36 6 144-0367 CLAMP PBT00315 1.8 6 In stock 12.46 74.76 1 230-2781 HOSE-UPPER + PBT00315 2.9 1 In stock 158.65 158.65 1 230-2782 HOSE-LOWER + PBT00315 5.4 1 In stock 85.20 85.20 1 10R-2129 PUMP AS WATE PBT00315 34.6 1 In stock 531.01 531.01 CORE CHARGE ++ 434.46 434.46 1 131-6645 HOSE AS. + PBT00315 0.3 1 In stock 9.54 9.54 1 224-2675 SEAL-PRESS I + PBT00315 0.1 1 In stock 11.23 11.23 2 335-9214 CLAMP-BAND	Major Repair
	3082	28/11/2013	COOLING SYSTEM	TAX ADJUSTMENT CREDIT NOTE PC0568362 -1 10R-2129 CORE CHARGE ++ 434.46 434.46	Major Repair
	5981	16/03/2013	INTAKE / EXHAUST SYSTEM	CHANGED AIR FILTER	Minor Repair

ENGINE	5981	15/03/2013	ENGINE REPAIR	1x 163-9361 engine oil filler cap	Minor Repair
	5981	15/03/2013	ENGINE REPAIR	ENGINE OIL FILLER CAP U/S ORDERED NEW OIL FILLER CAP	Minor Repair
	5845	8/02/2013	ENGINE REPAIR	Supply and fit engine filter hoses.	Minor Repair
	3141	20/02/2012	COOLING SYSTEM	Tax Inv PI6798128 1x 2S-6708 collector + cat a/f charge	Minor Repair
	3141	20/02/2012	COOLING SYSTEM	Tax Inv PI6812246 1x 242-7447 hose as	Minor Repair
	3141	15/02/2012	INTAKE / EXHAUST SYSTEM	Tax Inv PI6787526 1x 224-8171 hose	Minor Repair
	3141	15/02/2012	INTAKE / EXHAUST SYSTEM	Tax Inv PI6787525 1x 197-8418 gasket 1x 033-6033 'o' ring	Minor Repair
ENVIRONMENTAL	4047	4/04/2012	WEED AND SEED	WEED AND SEED EX02 - COOLGARDIE SITE Pressure ... Hire of Mobile Pressure Cleaner Water Supply water/per pod	Minor Repair
	4027	7/03/2012	WEED AND SEED	EX04 (Coolgardie site) Weed and Seed Pressure ... Hire of Mobile Pressure Cleaner Water Supply water/per pod	Minor Repair
HYDRAULIC SYSTEM	5499	29/04/2015	PUMPS / MOTORS	Tax Inv. # PI9628293 4* 4533447 BOLT 4* 4512182 WASHER Freight	Minor Repair
	5499	29/04/2015	PUMPS / MOTORS	Tax Inv. # PI9632484 1* 1141399 PIPE	Minor Repair

HYDRAULIC SYSTEM	5467	21/04/2015	HOSING / LINES	1* ELBOW 90` NPTF MALE X JIC MALE (L39.6MM) 1* ELBOW 6mm TUBE x 1/8 BSP (90 Deg) 1* NO 72 1/8X1/8 ADAPTOR 1* CUTTING RING - B3 1* TUBE NUT 1* BRAKE CLEANER 1* SERVICE CALL 1* PER HOUR	Minor Repair
	5343	31/03/2015	HYDRAULIC SYSTEM REPAIR	hose fittings	Minor Repair
	5343	26/03/2015	HOSING / LINES	hose as per sample	Minor Repair
	4676	14/11/2014	HOSING / LINES	HOSE AS PER SAMPLE	Minor Repair
	4475	20/10/2014	HOSING / LINES	QUICK HITCH HOSES	Minor Repair
	4370	30/09/2014	HOSING / LINES	4* 3/8 2 WIRE CRIMP ONLY THIN COVER 1* STR 3/8 1&2W 1 PC TL: 1 1/16 ORS FM SW 1* STR 3/8 1&2W 1 PC TL: 9/16 JIC FM SW 1* 90 SWPT 3/8 1&2W 1 PC TL: 11/16 ORS F 1* LABOUR	Minor Repair
	4335	23/09/2014	HOSING / LINES	1* grease line	Minor Repair
	4294	16/09/2014	HOSING / LINES	1* HOSE ASSEMBLY AS PER SAMPLE	Minor Repair
	4251	5/09/2014	HOSING / LINES	1* HOSE ASSEMBLY AS PER SAMPLE	Minor Repair
	7986	17/07/2014	HOSING / LINES	1* hose assembly	Minor Repair

HYDRAULIC SYSTEM	7931	11/06/2014	HYDRAULIC SYSTEM REPAIR	Tax Inv. # PI8850082 6 8T-4136 BOLT PBT00315 6 In stock .74 4.44 2 8T-4121 WASHER-HARD PBT00315 2 In stock .35 .70 1 095-1716 + O-RING PBT00315 1 In stock 4.38 4.38 5 159-7782 + SEAL PBT00315 5 In stock 9.34 46.70 1 095-1625 + O-RING PBT00315 1 In stock 5.02 15.06 1 8T-6759 PLUG PBT00315 1 In stock 3.39 3.39 6 8T-4121 WASHER-HARD PBT00315 6 In stock .35 2.10 6 8T-4136 BOLT PBT00315 6 In stock .74 4.44 1 8T-6404 + SEAL-O-RING Freight	Minor Repair
	7931	11/06/2014	HYDRAULIC SYSTEM REPAIR	Tax Inv. # PI8850083 2 095-1625 + O-RING PBT00315 2 Port Hedland Branch	Minor Repair
	7931	6/06/2014	HYDRAULIC SYSTEM REPAIR	elbow 381-6 SAE 100 R2 HOSE TYPE 1.25 41.38 51.73 1JS43-6-6 FEM SEAL -LOK S/W STRAIGHT 1 22.40 22.40 1J943-6-6 FEM SEAL LOK S/W 90 DEG 1 43.53 43.53 SGX20 PLASTIC SPRING GUARD (2643-20)	Minor Repair
	7690	16/04/2014	HOSING / LINES	Attend onsite Wellard train station compound manufacture hoses as requested by Mick	Minor Repair
	7603	1/04/2014	HOSING / LINES	Attend on site, manufacture and fit drive motor hose as requested by Mick	Minor Repair
	7603	28/03/2014	HOSING / LINES	BLOWN HYD HOSE REMOVE BLOWN LH TRAVEL MOTOR HOSE GET NEW HOSE MADE UP FIT NEW HOSE FILL WITH OIL AND WASH	Minor Repair
	3513	10/03/2014	HOSING / LINES	BLOWN HYD HOSE REMOVE ENGINE BAY PANELS AND WALKWAY TO IDENTIFY LEAKING HOSES, FOUND 1x HOSE RUBBED THROUGH AND 2 x HOSES IN POOR CONDITION, CONTACT HOSE MASTERS TO COME OUT AND MAKE HOSES	Minor Repair

HYDRAULIC SYSTEM	3489	1/03/2014	HYDRAULIC SYSTEM REPAIR	Tax Invoice No. PI8581090 1* 10R-2128 CORE AS OIL	Minor Repair
	3489	1/03/2014	HOSING / LINES	2* 224-6360 SEAL-PRESS	Minor Repair
	3456	22/02/2014	HYDRAULIC SYSTEM REPAIR	LOW OIL PRESSURE REPLACE OIL PUMP STRIP AND INSPECT OLD PUMP - CONDITION OK/ LIGHT SCORING AROUND OUTSIDE OF HOUSING	Minor Repair
	3245	18/01/2014	HOSING / LINES	REPLACED ADAPTORS ON EX02 @ THE VALE	Minor Repair
	3726	11/12/2013	HOSING / LINES	REPLACE 2X HYD HOSES ON CAT EXCAVATOR EX02 @ AMBERTON	Minor Repair
	6886	19/09/2013	HYDRAULIC SYSTEM REPAIR	hose as per sample	Minor Repair
	6886	17/09/2013	HOSING / LINES	1* 1 1/4" HOSE - 1.5 LONG HYD FILTER TO VALVE BLOCK LINE	Minor Repair
	6652	8/08/2013	HOSING / LINES	Supplied plugs and caps for EX02 as per Dave's request.	Minor Repair
	6513	9/07/2013	HOSING / LINES	SUPPLIED HYD HOSE FOR P# EX02 @ YANCHEP SITE	Minor Repair
	6513	5/07/2013	HYDRAULIC SYSTEM REPAIR	STEEL HYDRAULIC PIPE SPLIT CHECK PIPE WITH A. MOSS TRAVEL TO LOT 9, CHECK AVAILABILITY OF PIPE - EX SINGAPORE 5 DAYS ARRANGE FOR ENZED TO COME TO SITE TO MAKE A RUBBER HOSE UP.	Minor Repair
	6476	4/07/2013	HYDRAULIC SYSTEM REPAIR	SUPLIED HYD HOSE FOR EX 02 FOR EX02 @ LOT 9	Minor Repair
	5845	11/02/2013	HOSING / LINES	Supply and fit O Rings to relief valve.	Minor Repair
	5451	13/11/2012	HOSING / LINES	MAKE HOSE TO LENGTH TO SUIT, SUPPLY FITTING	Minor Repair
	5411	7/11/2012	HOSING / LINES	REPLACE HOSE ON HYD PUMP	Minor Repair
	5333	17/10/2012	HOSING / LINES	1x 236-3023 hose as	Minor Repair
	2827	24/10/2011	HOSING / LINES	to supply 1x cat hyd hose as per sample supplied	Minor Repair

HYDRAULIC SYSTEM	768	22/12/2010	HOSING / LINES	1x bucket tilt hose and fittings	Minor Repair
	493	1/11/2010	HOSING / LINES	TO MAKE UP 1X HYD HOSE AS PER SAMPLE BUCKET LINE]	Minor Repair
Job Defect		13/06/2015		HYDRAULIC LEAK UNDER ENGINE BAY	
		13/06/2015		DAMAGE TO ENGINE BAY PLATES	
		17/02/2015		FIRE EXTINGUISHER REQUIRES REPOSITIONING	
		17/02/2015		OIL LEAK AROUND SLEW	
		17/02/2015		SHIMS ON KNUCKLE U/S ???	
		17/02/2015		LEFT GREASE NIPPLE ON TOP OF KNUCKLE NOT TAKING GREASE ???	
		17/02/2015		HYD LEAK AT PUMP	
		17/02/2015		SLEW BRAKE FAULTY	
		17/02/2015		AIRCON FAULTY	
		18/10/2014		NEEDS SPACERS MAIN PIN ON QICK HITCH	
		18/10/2014		SLOW LEAK ON HYDRAULIC HOSE IN PUMP ROOM	
		9/10/2014		Flashing beacon inop	
		17/04/2014		ENGINE OIL FILLING EVERY 3 DAYS -	
		17/04/2014		LEAKING OIL	
		17/04/2014		SLEW RING	
		17/04/2014		BATTER BUCKET AND BUCKET PINS	
		3/12/2013		OVER HEATING HYD OIL/ COOLANT TEMP	
		3/12/2013		BENT DOOR (FIND OUT WHY AND SACK SOMEONE)	
		3/12/2013		BUCKET RAM CREEPS AND BUCKET NEEDS SHIMMING	
		3/12/2013		QUICK HITCH WONT OPEN	

Job Defect		3/12/2013		SLEW RING LEAKING OIL/GREASE	
		29/08/2013		operator reported bucket cylinder creeping	
		29/08/2013		inspect bucket shimms operator reports excessive movment	
		11/06/2013		BUCKET RAM CREEPS	
		30/05/2013		BUCKET RAM STARTING TO CREEP	
		30/05/2013		SAFETY CLAMP ON HITCH IS STICKY/ TEMPERAMENTAL	
		17/04/2013		GROUSER PLATES LOOSE,	
		17/04/2013		PUMP ROOM DOOR DAMAGED.	
		22/03/2013		AUTO GREASE ALARM KEEP GOING OFF	
		11/02/2013		FLASHING LIGHT	
		11/02/2013		LOOSE SCREW BUCKET	
		11/02/2013		BUCKET CRACKED	
		21/11/2012		grouser bolts loose	
		12/11/2012		QUICK HITCH NEEDS GREASING AND SOME NIPPLES TO BE REPLACED	
		12/11/2012		SOME GROUSER PLATES LOOSE	
		12/11/2012		1 MAIN HYD LINE FROM PUMP NEEDS TO BE REPLACED	
		12/11/2012		BATTERY BOX COMPARTMENT TO BE CLEANED OUT	
		27/09/2012		AIR CON WORKS ONLY SOMETIMES	
		27/09/2012		TRACK GUARDS VENT	
		27/09/2012		LH DOOR VEGIND CAB COMES OPEN	
		27/09/2012		RH TRACK MOTOR VERY WEAK	
		17/09/2012		Adjust tracks	

Job Defect		15/09/2012	AIR CON ONLY WORKS SOMETIMES	
		15/06/2012	FLASHING LIGHT NOT WORKING	
		21/04/2012	STEP DAMAGED	
		20/02/2012	CONCLUDE BUCKET REPAIRS, INCLUDING EXTRA WEAR STRIPS	
		20/02/2012	CONCLUDE AIR CON REPAIRS - OPERATORS TO KEEP CAB DOOR SHUT	
		20/02/2012	DETAIL CAB - PRODUCTION OPERATIONS	
		20/02/2012	WASH MACHINE COMPLETE	
		20/02/2012	REPAIR UNDERCARRAGE DAMAGE * 2 - NEAR IDLERS WHERE PRACTICLE	
		20/02/2012	3701 HRS - EX01 17-FEB	
		18/10/2011	BROKEN GREASE LINE ON BUCKET PIN	
		4/10/2011	Fuel hose leak in toolbox	
		2/06/2011	WIPER BLADES REQUIRE C/O	
		2/06/2011	TOOL BOX STEP DAMAGED - BOOK TO PRODUCTION	
		2/06/2011	ENGINE CUTS OUT IN MORNING - FUEL FAULT ?? REQUIRES PRIMING IN MORNINGS ??	
		2/06/2011	BUCKET RIBS CRACKED	
		19/04/2011	BOOM LAMPS OUT	
		1/02/2011	flashing light n-w	
		10/12/2010	COUNTER WEIGHT DAMAGE	
		9/11/2010	SEAT BELT STUCK	
		9/11/2010	L/H BOOM LAMP OUT	
		9/11/2010	REQUIRES NEW WIPER BLADE	

Job Defect		1/11/2010		FRONT WIPER REQUIRES REPLACING	
OTHER	5343	30/03/2015	EXTERNAL REPAIR	LABOUR HIRE OF G.HOOPER FROM 23/3/15 TO 28/3/15 AS PER ATTACHED TIMESHEETS	Minor Repair
	5343	24/03/2015	EXTERNAL REPAIR	LABOUR HIRE OF G.HOOPER FROM 16/03/15 TO 21/03/15 AS PER ATTACHED TIMESHEETS	Minor Repair
	5343	21/03/2015	OTHER MISCELLANEOUS ENTRIES	6* 8T-4136 BOLT 2* 8T-4121 WASHER-HARD 1* 095-1716 O-RING 5* 159-7782 SEAL 3* 095-1625 O-RING 1* 8T-6759 PLUG 2* 9X-4598 SEAL	Minor Repair
	5254	10/03/2015	EXTERNAL REPAIR	LABOUR HIRE OF G.HOOPER FROM 03/03/15 TO 07/03/15 AS PER ATTACHE TIMESHEETS	Minor Repair
	5193	24/02/2015	OTHER MISCELLANEOUS ENTRIES	Tax Inv. # PI9472874 2* 4H-6112 BREATHER 1* 135-9044 SEAL 2* 3K-0360 SEAL 2* 5P-2235 SEAL 7* 093-0084 SPACER 8* 093-0090 SPACER 8* 093-0116 SPACER 8* 093-0122 SPACER 1* 093-0090 SPACER 8* 093-0074 SPACER 2* 093-0106 SPACER 1* 349-7059 CAP AS-FUEL 1* 9P-7121 STRAINER	Minor Repair
	5193	24/02/2015	EXTERNAL REPAIR	LABOUR HIRE OF G.HOOPER AS PER ATTACHED TIMESHEET	Minor Repair

OTHER	5193	24/02/2015	OTHER MISCELLANEOUS ENTRIES	Tax Inv. # PI9476610 3* 135-9044 SEAL 1* 093-0084 SPACER 7* 093-0090 SPACER 8* 093-0122 SPACER 6* 093-0106 SPACER Freight	Minor Repair
	4229	3/09/2014	INTERNAL REPAIR	Grease up noisy stick pins and bearings	Minor Repair
	7955	8/07/2014	EXTERNAL REPAIR	1* LABOUR 1* BELLY GUARD Straightened track frames, Modified and fitted new belly guards	Minor Repair
	7955	7/07/2014	EXTERNAL REPAIR	1* LABOUR 1* ARROW HEAD 1* GROUSER BAR 1* WELDING WIRE 1* GAS Removed worn arrow head and ground lip up, Cut arrow head to size, tacked onto lip, pre-heated and fully welded to lip, Removed worn sections of side cutters, Cut grouser bar to size, tacked into position, pre-heated and fully welded, Repaired various cracks in shell and around ears	Minor Repair
	6802	2/09/2013	TRANSPORT/ COURIER	Inv No. U842 Transport Bucket for Maddington to Wellard	Minor Repair
	6242	22/05/2013	TRANSPORT/ COURIER	TAX INVOICE 51418	Minor Repair
	5960	11/03/2013	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSE FOR MECHANICAL REPAIRS @ METRO SITES. 4.5HRS @ \$80 DAILY MACHINE CHECKS INCLUDES CHARGES 67KM @ \$1.00 PER KM INVOICE PERIOD - 1-2-13 TO 28-2-13	Minor Repair

OTHER	5819	7/02/2013	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSE FOR MECHANICAL REPAIRS @ METRO SITES. 1.5HRS @ \$80 DAILY MACHINE CHECKS INVOICE PERIOD - 7-1-13 TO 31-1-13	Minor Repair
	5543	5/12/2012	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSE FOR MECHANICAL REPAIRS @ METRO SITES. 2HRS @ \$75 DAILY MACHINE CHECKS INVOICE PERIOD - 1-11-12 TO 17-11-12	Minor Repair
	5411	31/10/2012	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSE FOR MECHANICAL REPAIRS @ METRO SITES. 12.5HRS @ \$80 DAILY MACHINE CHECKS VEHICLE KM CHARGE 100KM @ \$1 PER KM INVOICE PERIOD - 2-10-12 TO 31-10-12	Minor Repair
	5333	19/10/2012	TRANSPORT/ COURIER	REMOVE HANDRAILS.	Minor Repair
	4473	21/07/2012	TRANSPORT/ COURIER	PREPARE MACHINE FOR TRAVEL	Minor Repair
	4376	24/05/2012	TRANSPORT/ COURIER	TOLL INVOICE 260	Minor Repair
	4047	4/04/2012	CONTRACTED LABOUR EXPENSE	CONTRACT LABOUR - AUTO ELECTRICIAN EX02 - COOLGARDIE SITE 28/03/2012 - Travel to site, replace hour meter on EX02, return to workshop Travel Travel to Coolgardie site and return Parts Hour Meter	Minor Repair
	4047	3/04/2012	CONTRACTED LABOUR EXPENSE	carry out welding of EX02 bucket Labour, Cut and and fit 16mm Hardox inside cheek plates weld out, Cut and fit Grouser Bar to top edge of cheek, Travel to site and return Parts 1 full length of grouser bar 16mm 800mmx800mm Hardox Plate	Major Repair

OTHER	4047	3/04/2012	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSES FOR REPAIRS CONDUCTED @ COOLGARDIE 29HRS @ \$95 AND 48.5HRS @ \$70	Minor Repair
	4027	31/03/2012	TRANSPORT/ COURIER	INV 0252 FREIGHT PARTS	Minor Repair
	4027	8/03/2012	CONTRACTED LABOUR EXPENSE	EX02 (Coolgardie Site) Welding Repairs Refurbish EX02 Bucket Welding ... Labour Hire Materials Consumables Travel Welder hire	Minor Repair
	4027	8/03/2012	PRODUCTION EXPENSE	charges for excessive wear/damages to machine (booked to production as advised by Peter Coggon)	Minor Repair
	4027	2/03/2012	PRODUCTION EXPENSE	CONTRACTED LABOUR EXPENSES FOR REPAIRS CONDUCTED @ COOLGARDIE 34HRS AT \$95 26.5HRS AT \$70	Minor Repair
	3141	15/02/2012	TRANSPORT/ COURIER	FREIGHT PARTS	Minor Repair
	3141	6/02/2012	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSES FOR REPAIRS CONDUCTED @ COOLGARDIE 11 HRS @ \$95	Minor Repair
	3141	19/01/2012	TRANSPORT/ COURIER	INVOICE 0242 FREIGHT FROM WESTRAC	Minor Repair
	3141	6/01/2012	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSES FOR REPAIRS CONDUCTED @ COOLGARDIE 34.5 HRS @ \$95 AND 24 HRS @ \$70	Minor Repair
	3141	19/12/2011	OTHER MISCELLANEOUS ENTRIES	1x 3077-7771 Sheet As	Minor Repair

OTHER	3141	19/12/2011	OTHER MISCELLANEOUS ENTRIES	12x 301-2299 Bolt Track 12x 150-4742 Nut Track	Minor Repair
	3141	19/12/2011	OTHER MISCELLANEOUS ENTRIES	Tax Inv PI6562369 6x 099-4691 Bolt	Minor Repair
	3141	19/12/2011	OTHER MISCELLANEOUS ENTRIES	Tax Inv PI6562367 Freight Recovery	Minor Repair
	2827	15/12/2011	TRANSPORT/ COURIER	FREIGHT	Minor Repair
	2827	5/12/2011	MACHINE CONSUMABLE ITEMS	20L DRUM WINDOW CLEANER 1X SOFT BLOW HAMMER 1x window cleaner 1x 42gm ultra grey 1x tape denso 50mmx 10m roll	Minor Repair
	2827	5/12/2011	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSES FOR REPAIRS CONDUCTED @ COOLGARDIE 31HRS @ \$95 AND 32HRS @ \$70	Minor Repair
	2827	2/12/2011	OTHER MISCELLANEOUS ENTRIES	Tax Inv PI6628046 1x GET pin removing tool 1x brass hammer	Minor Repair
	2827	30/11/2011	TRANSPORT/ COURIER	WESTRAC	Minor Repair
	2827	4/11/2011	CONTRACTED LABOUR EXPENSE	CONTRACTED LABOUR EXPENSES FOR REPAIRS CONDUCTED @ COOLGARDIE - 10HRS @ \$95 6HRS @ \$70	Minor Repair
	2332	15/09/2011	TRANSPORT/ COURIER	TRANSPORT BATTER BUCKET FROM BAILYES BOILERMAKING TO BUTLER RAIL DEPOT 3.5 HRS	Minor Repair
	1498	1/05/2011	TRANSPORT/ COURIER	COURIER CHARGES	Minor Repair

OTHER	179	25/09/2010	OTHER MISCELLANEOUS ENTRIES	1*Garden spade 2*500 ml armorral 1*Gloves	Minor Repair
	30	19/08/2010	MANUFACTURE NEW	new machine photos attached taken at w-trac prior to delivery 18/8/2010	Minor Repair
	30	4/08/2010	MANUFACTURE NEW	ATTACHED IS A COPY OF THE MACHINE BUILD DETAILS ALSO BUCKET INFO / MACHINE SPECS	Minor Repair
POWERTRAIN	6710	20/08/2013	SEGMENTS / DRIVESHAFTS	2* 124-3296 SPROCKET	Minor Repair
	6710	19/08/2013	SEGMENTS / DRIVESHAFTS	Tax Inv PI8122502 40* 7X-2575 BOLTS 8* 301-2299 BOLT 8* 150-4742 NUTS	Minor Repair
	6710	19/08/2013	SEGMENTS / DRIVESHAFTS	Tax Inv PI8136945 2* 124-3296 SPROCKET-TRK	Minor Repair
	6710	19/08/2013	SEGMENTS / DRIVESHAFTS	Tax Inv PI8136946 4* 2B-7561 CORK	Minor Repair
SAFETY	6710	22/08/2013	FIRE EXTS / FIRE SUPPRESSION	EX02 - 12 Month Fire Extinguisher Service Fire Extinguisher Service 9kg Labour Fire Ext. Bag	Minor Repair
	5333	20/10/2012	STEPS / HAND RAILS	REFIT HAND RAILS. INSTALL CYLINDER PINS.	Minor Repair
SERVICING	5292	18/03/2015	SERVICING EXPENSE	4 x7M8485 1 x 7Y1647 1 x 9X8600 1 x 1484704	Servicing
	5193	24/02/2015	SERVICING EXPENSE	1* 293 1137 1* 245 7823 1* 245 7824	Servicing
	5152	19/02/2015	SERVICING EXPENSE	1* 2931183 filter 1* 2931184 filter	Servicing

SERVICING	4523	29/10/2014	SERVICE KIT ORDER	Tax Inv No. PI9210210 1* RJV142 - 500HR SERVICE KIT 00C481659	Servicing
	4434	15/10/2014	SERVICING EXPENSE	1* 2931137 AIR CON FILTER 1* 2457823 AIR CON FILTER	Servicing
	4251	9/09/2014	SERVICE KIT ORDER	Tax Inv. # PI9092833 1* RJV142 - 500HR SERVICE KIT 00C425749	Servicing
	7955	2/07/2014	SERVICE KIT ORDER	Tax Inv. # PI8909082 1* RJV144 2000HR SERVICE KIT	Servicing
	7603	31/03/2014	SERVICE KIT ORDER	1* RJV143 1000HR SERVICE KIT	Servicing
	7031	20/11/2013	SERVICE KIT ORDER	1* RJV143 1000HR SERVICE KIT	Servicing
	7031	20/11/2013	SERVICE KIT ORDER	1* HIT000034 500HR SERVICE KIT	Servicing
	6513	9/07/2013	SERVICE KIT ORDER	1* RJV142 500HR SERVICE KIT	Servicing
	5981	21/03/2013	SERVICE KIT ORDER	1* RJV144 2000hr service kit	Servicing
	5502	23/11/2012	SERVICE KIT ORDER	1* RJV 142 500hr service kit	Servicing
	5215	3/10/2012	SERVICING EXPENSE	carried out 1000hr service	Servicing
	5085	6/09/2012	SERVICE KIT ORDER	1* RJV143 1000hr service kit	Servicing
	4473	19/06/2012	SERVICE KIT ORDER	1* RJV142 500hr service kit	Servicing

SERVICING	4027	19/03/2012	SERVICE KIT ORDER	1x RJV170 2000hr service kit. *send straight to Kalgoorlie cutting edges for pick up by Melia mechanical*	Servicing
	3141	2/02/2012	SERVICE KIT ORDER	1x RJV168 for 500hr service	Servicing
	2827	29/11/2011	SERVICE KIT ORDER	Tax Inv PI6613055 1X RJV143 1000HR SERVICE KIT REF; 01C 556514	Minor Repair
	2827	8/11/2011	SERVICE KIT ORDER	250HR SERVICE KIT	Servicing
	2421	13/10/2011	SERVICE KIT ORDER	Tax Inv PI6512105 500HR SERVICE KIT	Minor Repair
	2040	27/07/2011	VEHICLE SERVICE	ASSIST SERVICE - 2000HR	Servicing
	1989	22/07/2011	SERVICE KIT ORDER	Tax Invoice No. 2952296 2000 HR SERVICE PARTS 1* 1R 0755 FILTER 1* 1R 1808 FILTER 1* 5I 8670 FILTER 1* 7M 8485 SEAL 1* 7Y 1647 GASKET 1* 9X 2205 FILTER KIT 1* 9X 8600 O RING 1* 9Y 1758 GASKET 1* 093 7521 FILTER 1* 106 3969 ELEMENT AS 1* 106 3973 ELEMENT AS 1* 1232003 SEAL 1* 148 4704 GASKET 1*179 9806 ELEMENT 1* 201 9299 SERVICE KIT 1* 229 5711 SEAL-ISOLATI 1* 326 1643 FILTER SAMPLE BOTTLERS FOR 2000 HR SERVICE - EXCAVATOR	Servicing

SERVICING	1498	2/05/2011	SERVICE KIT ORDER	Tax Inv PI6141529 1* RJV 142 500 HR SERVICE KIT 00C: 126 161	Servicing
	1399	12/04/2011	SERVICING EXPENSE	3X 293 1184 CAB FILTER 00C091735	Minor Repair
	1151	3/03/2011	AIR FILTERS	Invoice Number PI6022642 1* 106 3969 AIR FILTER	Servicing
	1050	16/02/2011	VEHICLE SERVICE	Invoice Number SI0767111 TO PERFORM 1000HR MECHANICAL INSPECTION ON SITE AS PER WARRENTY REQUIREMENTS RJV SERVICEMAN TO CONDUCT SERVICE PROJECT LOCATION - CAPTIVA APPROACH SOUTHERN GATE ACCESS - CODE 0707	Servicing
	1050	14/02/2011	SERVICE KIT ORDER	PI5986193 1* RJV 143 1000HR SERVICE KIT 00C: 055 619	Servicing
	542	9/11/2010	SERVICE KIT ORDER	Invoice Number PI5811448 1* RJV 142 500 HR SERVICE KIT	Servicing
	179	24/09/2010	SERVICE KIT ORDER	3x 1063973 air filters	Servicing
	179	24/09/2010	SERVICE KIT ORDER	1x rjv142 500hr service kit	Servicing
SYSTEMS	5467	20/04/2015	GROUND ENGAGING TOOLS	5* 2862110 RETAINER	Minor Repair
	4783	4/12/2014	GROUND ENGAGING TOOLS	Repaired cracks in lip and adaptors Replaced missing lip protection eg: grouser bar and arrow head	Minor Repair

SYSTEMS	4523	30/10/2014	AUTO GREASER	2* SL-1 INJECTOR WITH BOLT	Minor Repair
	4335	25/09/2014	GROUND ENGAGING TOOLS	5* 2862117 TIPS 5* 2862110 PINS	Minor Repair
	3303	28/01/2014	GROUND ENGAGING TOOLS	INV NO. PI 8495784 5* 286-2117 TIP GENERAL	Minor Repair
	3303	28/01/2014	GROUND ENGAGING TOOLS	Inv No. PI8495783 04C200103 5* 286-2117 TIP GENERAL 10* 286-2110 RETAINER GET	Minor Repair
	3245	23/01/2014	AUTO GREASER	REPLACE GREASE LINE ON BOOM	Minor Repair
	6476	4/07/2013	GROUND ENGAGING TOOLS	WORN RIPPER BOOT INSTALL 1X NEW BOOT AND PIN	Minor Repair
	6433	25/06/2013	AUTO GREASER	BUCKET LINKAGE GREASE LINE U/S MACHINE POSSIBLY OVER GREASING REPLACED U/S GREASE LINE. CHECK GREASER CYCLE TIMES AND PARAMETERS ALL ARE IN ACCORDANCE OF GREASEER MANUFACTURE SPECIFICATIONS TO THIS SIZE MACHINE. ADJUST GREASER TIME TO A SLOWER TIME PERIOD (FOR A SMALLER MACHINE)	Minor Repair
	6242	17/05/2013	AUTO GREASER	1* 525-32083-1 solenoid valve 24vdc + freight	Minor Repair
	6220	15/05/2013	AUTO GREASER	1* NLS03-000014 cycle timer 1* spg063-00400-01-s-b04 gauge	Minor Repair
	5333	29/10/2012	GROUND ENGAGING TOOLS	10 1D-4637 CAP SCREW 10 2J-3507 NUT 10 3K-5234 WASHER	Minor Repair
	5215	28/09/2012	AUTO GREASER	Attend on site and manufacture grease hose as requested by Craig	Minor Repair

SYSTEMS	4027	1/03/2012	GROUND ENGAGING TOOLS	Tax Inv PI6824953 12x 286-2117 tips	Minor Repair
	4027	1/03/2012	GROUND ENGAGING TOOLS	Tax Inv PI6824952 6x 286-2117 tips 18x 286-2110 Retainer get	Minor Repair
	3141	13/02/2012	GROUND ENGAGING TOOLS	6x 286-2117 tips	Minor Repair
	3141	3/02/2012	GROUND ENGAGING TOOLS	Tax Inv PI6759266 7x 286-2117 bucket teeth	Minor Repair
	3141	3/02/2012	GROUND ENGAGING TOOLS	Tax Inv PI6759267 12x 286 2110 retainers	Minor Repair
	3141	3/02/2012	GROUND ENGAGING TOOLS	Tax Inv PI6798127 5x 286-2117 bucket teeth	Minor Repair
	3141	3/02/2012	GROUND ENGAGING TOOLS	Tax Adjustment Credit Note PC0471916 12x 286-2110 Retainer	Minor Repair
	3141	2/02/2012	GROUND ENGAGING TOOLS	Tax Inv PI6683064 1x 256-8691 sidecutter L 01c560716B 1x 1D-4637 cap screw	Minor Repair
	3141	2/02/2012	GROUND ENGAGING TOOLS	1x 1D 4637 cap screw	Minor Repair
	3141	2/02/2012	GROUND ENGAGING TOOLS	1x 326-3406 side cutter-L	Minor Repair

SYSTEMS	3141	2/02/2012	GROUND ENGAGING TOOLS	1x 326-3405 side cutter-R	Minor Repair
	3141	2/02/2012	GROUND ENGAGING TOOLS	Tax Invoice PI6691918 5x 2J 3507 nut 01c561276A	Minor Repair
	3141	2/02/2012	GROUND ENGAGING TOOLS	Tax Invoice PI6691919 1x 326-3405 sidecutter	Minor Repair
	3141	2/02/2012	GROUND ENGAGING TOOLS	Adjustment Note PC0466116 1x 256-8691 sidecutter L	Minor Repair
	3141	16/01/2012	GROUND ENGAGING TOOLS	Tax Inv PI6729368 6x 286 2117 bucket teeth	Minor Repair
	3141	16/01/2012	GROUND ENGAGING TOOLS	Tax Inv PI6715759 01c562785 6x 286 2110 retainers 6x 286 2117 bucket teeth	Minor Repair
	3141	16/01/2012	GROUND ENGAGING TOOLS	Tax Adjustment Credit Note PC0468829 6x 286 2117 bucket teeth	Minor Repair
	3141	4/01/2012	GROUND ENGAGING TOOLS	Tax Inv PI6689149 1x 5T-9982 plate as	Minor Repair
	3141	4/01/2012	GROUND ENGAGING TOOLS	Tax Inv PI6689147 1x 1D-4637 cap screw 5x 2J-3507 Nut	Minor Repair
	3141	4/01/2012	GROUND ENGAGING TOOLS	Tax Inv PI6689148 4x 1D-4637 cap screw	Minor Repair
	2827	12/12/2011	GROUND ENGAGING TOOLS	Tax Inv PI6648363 5X 286 2110 RETAINERS 10X 301 2299 GROUSER BOLTS	Minor Repair

SYSTEMS	2827	12/12/2011	GROUND ENGAGING TOOLS	Tax Inv PI6660059 10X 150 4742 GROUSER NUTS	Minor Repair
	2827	12/12/2011	GROUND ENGAGING TOOLS	Tax Inv PI6648362 12X 220 9119 BUCKET TEETH 7X 286 2110 RETAINERS 6X 2862110 RETAINERS	Minor Repair
	2827	12/12/2011	GROUND ENGAGING TOOLS	Tax Inv PI6648364 6X 2862117 TIP GENERAL	Minor Repair
	2827	5/12/2011	AUTO GREASER	GREASE HOSES FOR EX02	Minor Repair
	2827	1/12/2011	GROUND ENGAGING TOOLS	6x 286 2117 bucket teeth 6x 286 2110 retainers	Minor Repair
	2827	14/11/2011	GROUND ENGAGING TOOLS	Tax Inv PI6582054 BUCKET TEETH FOR EX02	Minor Repair
	2827	9/11/2011	GROUND ENGAGING TOOLS	G.E.T. BUCKET TEETH FOR EX 02 7x 2862113 TIP PENE	Minor Repair
	2827	9/11/2011	GROUND ENGAGING TOOLS	G.E.T. BUCKET TEETH FOR EX 02 1x 2862110 RETAINER GET	Minor Repair
	2827	9/11/2011	GROUND ENGAGING TOOLS	G.E.T. BUCKET TEETH FOR EX 02 6x 2862110 RETAINER GET	Minor Repair
	2421	13/10/2011	GROUND ENGAGING TOOLS	Tax Inv PI6512100 G.E.T BUCKET TEETH	Minor Repair
	2421	4/10/2011	AUTO GREASER	TO REMOVE / REPLACE AND EXCHANGE DAMAGED BUCKET GREASE LINES AS REQUIRED CALL OUT FEE INCORPORATED	Minor Repair
	1989	21/07/2011	AUTO GREASER	FIT NEW GREASE FITTING TO SLEW HOUSING	Minor Repair

SYSTEMS	1897	8/07/2011	GROUND ENGAGING TOOLS	1* 10WE120-HD WELD ON LEADING EDGE ADAM IS THE CONTACT - ETA 15-07-2011	Minor Repair
	1848	30/06/2011	GROUND ENGAGING TOOLS	REFIT CUTTING EDGES - BATTER BUCKET	Minor Repair
	1050	16/02/2011	AUTO GREASER	SUPPLY AND FIT GREASE LINE AS PER SAMPLE	Minor Repair
	1050	16/02/2011	GROUND ENGAGING TOOLS	TENSION BUCKET GOANNAS - LOOSE	Minor Repair
	124	7/09/2010	AUTO GREASER	TO SUPPLY FITTINGS AS PER SAMPLE FOR GREASE POT FILLING	Minor Repair
UNDERCARRIAGE	5343	24/03/2015	TRACKS	1* TRACK LINK AS M/P 1L 1* SLIP FIT M/PIN AND LOCK 12* TRACK BOLTS 13* TRACK NUTS 5* TRACK PRESS inc 2 TECHNICIANS 2* TRAVEL TO AND FROM 1* REMOVE LINK SECTION 1* CONVERT TO SLIP FIT MASTER 1* LOAD AND UNLOAD	Minor Repair
	3082	26/11/2013	TRACK FRAMES	1* set 345DL tracks 52 links clearance fit master link	Major Repair
	6980	11/11/2013	TRACKS	WORN DRIVE SPROCKETS REMOVE TRACK REMOVE DRIVE SPROCKET REPLACE DRIVE SPROCKET WITH NEW PUT TRACK BACK ON PUMP UP TRACK	Minor Repair
	6943	31/10/2013	TRACKS	40* 7X-2575 BOLT	Minor Repair
	5411	31/10/2012	TRACKS	40x 301-2299 bolt track 40x 150-4742 nut-track 10x 1D-4637 bolt 10x 2J-3507 nut 10x 3K-5234 washer	Minor Repair

UNDERCARRIAGE	5215	3/10/2012	TRACKS	30x 301-2299 bolt track 30x 150-4742 nut-track	Minor Repair
	3141	9/01/2012	UNDERCARRIAGE REPAIR	Tax inv PI6701970 DAMAGED ON SITE 1X 134-8894 PLATE AS 1X 134-8896 PLATE AS	Operator Damage
	3141	9/01/2012	UNDERCARRIAGE REPAIR	Tax Inv PI6698884 DAMAGED ON SITE 6X 8C-8992 BOLT 6X 5P-1076 WASHER	Operator Damage
	3141	9/01/2012	UNDERCARRIAGE REPAIR	Tax Inv PI6698885 DAMAGED ON SITE 6X 8T-3597 NUT	Operator Damage
	2327	9/09/2011	UNDERCARRIAGE REPAIR	Replace 8 grouser bolts and nuts Straighten righthand step	Minor Repair
	2196	23/08/2011	TRACKS	removed 4x grouser plate bolts and install new bolts	Minor Repair
	2153	16/08/2011	TRACKS	24x 301 2299 bolts 24x 150 4742 nuts	Minor Repair
	1720	9/06/2011	TRACKS	replaced missing grouser pads bolts and nuts	Minor Repair
	1686	31/05/2011	TRACKS	Invoice Number PI6198656 6x 301 2299 bolt track 6x 150 4742 nut track 00C 150 941	Minor Repair
	1639	27/05/2011	TRACKS	6X 301 2299 BOLT 6X 150 4742 NUT	Minor Repair