

ACN: 108 930 089

ABN: 64 108 930 089

Client:	All Used Equipment			Site:	230-232 Welshpool Road		
Date:	02/08/2023	Job#:	34171	Asset No:	C150D2R		

RESIDUAL CURRENT DEVICE CHECKS

RCD No. or Description	mA Rating	CURRENT & TRIP TIME											
		mA Rating x ½				mA Rating x 1				mA Rating x 5			
		0°		180°		0°		180°		0°		180°	
		mA	mS	mA	mS	mA	mS	mA	mS	mA	mS	mA	mS
Earth leakage	100	50	N/t	50	N/t	100	N/t	100	N/t	500	N/t	500	N/t
Outlet 1	30	15	N/t	15	N/t	30	89	30	89	150	89	150	89
Outlet 2	30	15	N/t	15	N/t	30	17.1	30	17.2	150	9.5	150	8.7
Outlet 3	30	15	N/t	15	N/t	30	17	30	17.5	150	9.5	150	9.5

INSULATION TESTING


Description	Volt Grade	Test Volts	Insulation Resistance (Ω)					Phase & Earth Resistance	Termination & Cable No. check	
			R-W	R-B	B-W	RWB-N	RWB-E		Origin	Dest.
			Alternator	415	1000	0.1	0.1		0.1	-
Main Switch	415	1000	999M	999M	999M	999M	999M	0.07	Alternator	Main switch
Outlet 1	240	500	999M	999M	999M	999M	999M	0.07	Main switch	Outlet 1
Outlet 2	240	500	999M	999M	999M	999M	999M	0.09	Main switch	Outlet 2
Outlet 3	415	1000	999M	999M	999M	999M	999M	0.07	Main switch	Outlet 3
Marechal outlet	415	1000	999M	999M	999M	999M	999M	0.07	Main switch	Marechal outlet

COMMENTS:

Earth Leakage does not work

RCD Test Date:	02/08/2023	Next Test Date:	02/08/2023	EWL#:	13100
-----------------------	------------	------------------------	------------	--------------	-------

I certify that all electrical tests were carried out to suit all the requirements of the Electricity (Licensing) Regulations 1991.

Electrician Name:	Billy Hutchinson	Electrician Signature:	
--------------------------	------------------	-------------------------------	---