

Ordered From:

All Used Equipment
230-232 Welshpool Rd
Welshpool WA 6106, Australia

Quote No: PCWR4746
Quote Date: 17/11/2023
Sales Person: Katherine Yeates
Quote Expiry: 17/12/2023
Currency: AUD
Page: 1 of 1

Bill To:

ALL USED EQUIPMENT
230-232 Welshpool Rd
Welshpool WA 6106, Australia

Instructions:

18" heater
AUE-HP02

Line #	Code & Description	Unit	Qty	Req Date	Unit Price	Ext Price
10	WS REPAIR <i>Workshop repair</i>	Each	4	17/11/2023	\$200.00	\$800.00
	Line Notes: *Replace the damaged Butt plate and tidy up the edges of the heater body, so that the butt plates sit flat on the body. This will ensure that the temperature in move even. *Replace the heater handle power cord strain relief. *Reconnect the neutral wire that has come out of the heater PCB terminal block. *Replace the torn heater bags. *Test the RTD and the Element, both tested OK. *Test and tag. *Run the heater plate up to the set temperature, and check the average temperature, of set if needed.					
20	A1852013 <i>18 LW HTR BUTT PLATE KIT</i>	Each	1	17/11/2023	\$1647.70	\$1647.70
30	434302 <i>POWER CORD STRAIN RELIEF</i>	Each	1	17/11/2023	\$21.84	\$21.84
40	1835303 <i>INSULATED HEATER PANEL SET</i>	Each	1	17/11/2023	\$1046.77	\$1046.77

Nett Total: \$3516.31
GST Total: \$351.63
Total: \$3867.94